

Vehicle Inspection Form

Inventory ID: 38854	Asset Number:	Fair Market Value:
Short Description: Year <u>2019</u> Make <u>Ford</u> Model <u>F250</u>		
VIN: <u>1FT7X2B67KEG51686</u>	Title: ☒ Clean Title ☐ Salvage Title ☐ No Title ☐ Court Documents Only ☐ SF97 Form ☐ Other	
Odometer: <u>160494</u> ☒ Miles ☐ Kilometers ☐ Hours	Odometer Accurate? ☐ Yes ☐ No ☐ Unknown	
Long Description: This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Drivable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u>6.2</u> L, V ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: _____ This vehicle was maintained every _____ ☐ Days ☐ Hours ☐ Miles/Kilometers Date Removed from Service: _____ Maintenance Records: ☐ Available ☐ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual _____ Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: _____ Drivetrain: ☐ 2 Wheel Drive ☒ 4 Wheel Drive Condition: <u>works</u> Exterior: Color: <u>Gray</u> Windows: ☒ No Cracked Glass ☐ Cracked Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: <u>OK</u> Tread: <u>5mm</u> #Flat <u>0</u> Hubcaps # <u>3</u> Major Damage to: _____ Additional Damage: _____ Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No impressions Emergency equip: ☐ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes Interior: Color <u>Gray</u> ☐ Cloth ☒ Vinyl ☐ Leather Damage to Seats: _____ Damage to Dash/Floor: _____ Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD AC Condition: ☒ Cold ☐ Unknown ☐ No AC Air Bags: ☐ Driver's Side ☐ Dual ☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☒ Climate Control Power: ☒ Steering ☒ Windows ☒ Door Locks ☐ Seats		
Additional Equipment: <u>Winch carrier</u> <u>B&W Baller - Goose neck</u> Manufacturer _____ Model _____ Serial # <u>Hitch</u> ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____		
Location of Asset: <u>LR, AR</u>		

Pre Scan Vehicle System Report

VEHICLE INFORMATION

VIN	1FT7X2B67KEG51686
MAKE	Ford
YEAR	2019
MODEL	F-Series
ENGINE	6.2L V8 2V SOHC SEFI
SYSTEM	CodeScan
LICENSE PLATE	
ODOMETER	160494 mi

CODE SCAN RESULTS

Systems Analyzed: 20

- ✓ Engine: 0
- ✓ Transmission: 0
- ✓ Battery Energy Control Module B: 0
- ✓ Body Control Module: 0
- ✓ Tire Pressure Monitor: 0
- ✓ Antilock Brakes: 0
- ✓ Airbag: 0
- ✓ Audio Control Module: 0
- ✓ Body Control Module B: 0
- ✓ Controls Interface Module - Front: 0
- ✓ Door Module - Driver's: 0
- ✓ Door Module - Passenger's: 0
- ✓ Gateway Module A: 0
- ✓ Instrument Panel Control Module: 0
- ✓ Radio Transceiver Module: 0
- ✓ Steering Column Control Module: 0
- ✓ Tire Pressure Monitor:Radio Transceiver Module: 0
- ✓ Trailer Brake Control Module: 0
- ✓ Trailer Module: 0
- ✓ Transfer Case Control Module: 0
- ✓ OBDII Codes (\$03): 0
- ✓ OBDII Permanent Codes (\$0A): 0
- ✓ OBDII Pending Codes (\$07): 0

READINESS MONITORS

Tests Complete

- ✓ Misfire
- ✓ Fuel System
- ✓ Comprehensive Component
- ✓ EGR/VVT
- ✓ Catalyst
- ✓ Evaporative System
- ✓ Oxygen Sensor
- ✓ Oxygen Sensor Heater

