

Bus Inspection Form

Inventory ID <u>Bus 14</u>	Asset Number <u>765</u>	Fair Market Value:
Short Description: Year <u>2009</u> Make <u>Chevrolet</u> Model <u>Express</u>		
VIN: <u>1G1B5G316X91131114</u>		Title Restriction: <input type="checkbox"/> Y <input checked="" type="checkbox"/> N
Mileage/Odometer: <u> </u>		Odometer Accurate <input type="checkbox"/> Y <input type="checkbox"/> N:
Long Description: Primary use for Bus: _____ # of Passengers: _____ This vehicle: <input type="checkbox"/> Starts <input type="checkbox"/> Starts with a Boost and <input type="checkbox"/> Runs <input type="checkbox"/> Does Not Run <input type="checkbox"/> For Parts Only Engine Manufacture: _____ Engine Type: <u>6.6</u> L, V <u>8</u> <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel Engine This Vehicle was maintained every _____ <input type="checkbox"/> Days <input type="checkbox"/> Hours <input type="checkbox"/> Miles Engine Condition: <input type="checkbox"/> Runs <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition Repairs needed: _____ Date Removed From Service: _____ Maintenance Records: <input type="checkbox"/> Available <input type="checkbox"/> Not Available Transmission Manufacture: _____ <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual _____ Speed Transmission Condition is: <input type="checkbox"/> Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Unknown <input type="checkbox"/> Rebuilt (Date: _____) Repairs Needed: _____ Date Removed From Service: _____ Maintenance Records: <input type="checkbox"/> Available <input type="checkbox"/> Not Available For Inspection		
Exterior Description: Color: <u>Yellow</u> Windows: <input checked="" type="checkbox"/> No Cracked Glass <input type="checkbox"/> Cracked _____ Minor: <input type="checkbox"/> Dents <input type="checkbox"/> Scratches <input type="checkbox"/> Dings Tire Condition: <input type="checkbox"/> Low <input type="checkbox"/> Flat _____ Damage to: _____ Additional Damage to: _____ Decals: <input type="checkbox"/> None <input type="checkbox"/> Have been Sprayed Over <input type="checkbox"/> Have been removed & <input type="checkbox"/> Impressions Remain <input type="checkbox"/> No Impressions Other Exterior Information: _____		
Interior Description: Color <u>Blue</u> <input checked="" type="checkbox"/> Vinyl <input type="checkbox"/> Cloth <input type="checkbox"/> Leather Damage to Seats: _____ Damage to Dash/Floor: _____ Radio: Brand _____ <input type="checkbox"/> AM <input type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD Air Conditioning: <input type="checkbox"/> Yes <input type="checkbox"/> No AC Operating Condition: <input type="checkbox"/> Cold <input type="checkbox"/> Unknown Other Interior Information/Options: _____ Other Equipment: Description _____ Manufacturer _____ Model _____ Serial # _____		
Location of Asset: <u>Lee County DVS Shop</u> For more information contact: <u>David 276-973-8323</u>		