

Bus Inspection Form

Inventory ID <u>Bus 89</u>	Asset Number <u>767</u>	Fair Market Value:
Short Description: Year <u>2003</u> Make <u>Freightliner</u> Model _____		
VIN: <u>4U2AAAL83CK76329</u>		Title Restriction: ☐ Y ☒ N
Mileage/Odometer: <u>194880</u>		Odometer Accurate ☒ Y ☐ N:
Long Description: Primary use for Bus: _____ # of Passengers: _____ This vehicle: ☐ Starts ☐ Starts with a Boost and ☒ Runs ☐ Does Not Run ☐ For Parts Only Engine Manufacture: _____ Engine Type: <u>7.2 L, V</u> <u>LL</u> ☐ Gas ☒ Diesel Engine This Vehicle was maintained every _____ ☐ Days ☐ Hours ☐ Miles Engine Condition: ☐ Runs ☐ Needs repair ☐ Is in Unknown Condition Repairs needed: _____ Date Removed From Service: _____ Maintenance Records: ☐ Available ☐ Not Available Transmission Manufacture: _____ ☐ Automatic ☒ Manual _____ Speed Transmission Condition is: ☐ Operable ☐ Needs Repair ☐ Unknown ☐ Rebuilt (Date: _____) Repairs Needed: _____ Date Removed From Service: _____ Maintenance Records: ☐ Available ☐ Not Available For Inspection		
Exterior Description: Color: <u>Yellow</u> Windows: ☒ No Cracked Glass ☐ Cracked Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: ☐ Low ☐ Flat Damage to: _____ Additional Damage to: _____ Decals: ☐ None ☐ Have been Sprayed Over ☐ Have been removed & ☐ Impressions Remain ☐ No Impressions Other Exterior Information: _____		
Interior Description: Color <u>Gray</u> ☒ Vinyl ☐ Cloth ☐ Leather Damage to Seats: _____ Damage to Dash/Floor: _____ Radio: Brand _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD Air Conditioning: ☐ Yes ☐ No AC Operating Condition: ☐ Cold ☐ Unknown Other Interior Information/Options: _____		
Other Equipment: Description _____ Manufacturer _____ Model _____ Serial # _____		
Location of Asset: <u>Lee County Bus Shop</u> For more information contact: <u>DAVID 276-973-8323</u>		