Vehicle Inspection Form

Inventory ID:	Asset Number:	Fair Market Value:
Short Description: Year <u>2003</u> Make <u>International</u> Model 7400 4x2		
VIN: 1HTWOAAR 33JOL8814 Title: Clean Title Salvage Title No Title Court Documents Only SF97 Form Other		
Odometer: Unknown Miles Kilometers Hours Odometer Accurate? Yes No Unknown		
Long Description: This Vehicle: Starts Starts with a Boost & Runs/Drivable Engine Runs Does Not Run For Parts Only Engine- Type: L, V Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid Engine Condition: Runs Needs repair is in unknown condition Repairs needed: This vehicle was maintained every Days Hours Miles/Kilometers		
Date Removed from Service: Unknown Maintenance Records: Available Not Available For Inspection		
Transmission: Automatic Manual 10 Speed Condition: Operable Needs repair Is Unknown Condition Repairs Needed:		
Drivetrain: Wheel Drive 4 Wheel Drive Condition: Unknown		
Exterior: Color: White Windows: No Cracked Glass Cracked Minor: Dents Scratches Dings Tire Condition: Bad Tread: #Flat ## Hubcaps # O Major Damage to: Dody and hed is all had. Frame is rusted out. Additional Damage: Decals: None Have Been Sprayed Or Have been Removed & Impressions Remain No impressions Emergency equip: None Has been removed & There are holes in the exterior There are no holes Interior: Color Oray # Blue Color Co		
Additional Equipment: Manufacturer Model Serial # Tool Box Light Bar Ladder Rack Utility Body: Brand Hitch: Type		
Location of Asset:		