Vehicle Inspection Form <a>R4

Short Description: Year 2009 Make Chery Box & truck Model Salves ado 3500 HD VIN: 16BJC74k89E102750 Title: Clean Title Salvage Title No Title Court Documents Only SF97 Form Other
Court Documents Only SF97 Form Other
Odometer: Unknown Miles Kilometers Hours Odometer Accurate? Yes No Unknown
Long Description:
This Vehicle: Starts Starts with a Boost & Runs/Drivable Engine Runs Does Not Run For Parts Only
Engine- Type: 6.0 L, V S Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid
Engine Condition: Runs Needs repair is in unknown condition
Repairs needed: Days Hours Miles/Kilometers
Date Removed from Service: Maknown Maintenance Records: Available Not Available For Inspection
Transmission: Automatic Manual Speed Condition: Operable Needs repair is Unknown Condition
Repairs Needed:
Drivetrain: 2 Wheel Drive 4 Wheel Drive Condition:
Exterior: Color: White Windows: No Cracked Glass Cracked
Minor: Dents Scratches Dings Tire Condition: Tread: #Flat / Hubcaps # 0
Major Damage to: Has been wrecked
Additional Damage:
Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No impressions
Emergency equip: None Has been removed & There are holes in the exterior There are no holes
Interior: Color Grey 4 Black Cloth Vinyl Leather
Damage to Seats tore up
Radio: Stock or Brand & Model: AM/FM AM/FM Cassette AM/FM CD
AC Condition: Cold Conknown No AC Air Bags: Driver's Side Dual
Cruise Control Remote Mirrors Climate Control
Power: Vicering Windows Door Locks Seats
Additional Equipment:
Manufacturer Model Serial #
Tool Box Light Bar Ladder Rack Utility Body: Brand Hitch: Type
Location of Asset: