

Vehicle Inspection Form

Inventory ID: _____

Asset Number: _____

Fair Market Value: _____

Short Description:

Year 2012 Make International Model Pak Mor (garbage Truck)

VIN: 1HTWCAAR8CJ672068 Title: ☒ Clean Title ☐ Salvage Title ☐ No Title
☐ Court Documents Only ☐ SF97 Form ☐ Other

Odometer: Unknown ☐ Miles ☐ Kilometers ☐ Hours Odometer Accurate? ☐ Yes ☐ No ☐ Unknown

Long Description:

This Vehicle: ☐ Starts ☐ Starts with a Boost & ☐ Runs/Drivable ☐ Engine Runs ☒ Does Not Run ☐ For Parts Only

Engine- Type: 466 L, V ☐ Gas ☒ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☐ Runs ☒ Needs repair ☐ is in unknown condition

Repairs needed: Motor is shot. Motor has been took apart and looked at.

This vehicle was maintained every 3 to 5,000 ☐ Days ☐ Hours ☒ Miles/Kilometers

Date Removed from Service: Unknown Maintenance Records: ☐ Available ☐ Not Available For Inspection

Transmission: ☐ Automatic ☒ Manual 6 Speed Condition: ☒ Operable ☐ Needs repair ☒ Is Unknown Condition

Repairs Needed: _____

Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: good

Exterior: Color: White Windows: ☐ No Cracked Glass ☒ Cracked Wind sheild

Minor: ☐ Dents ☐ Scratches ☐ Dings Tire Condition: good Flat Tread: good #Flat 1 Hubcaps # _____

Major Damage to: _____

Additional Damage: Rust and parts missing

Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☐ Impressions Remain ☐ No impressions

Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior: Color grey and black ☐ Cloth ☐ Vinyl ☒ Leather

Damage to Seats: Hole in passenger seat

Damage to Dash/Floor: Dash good. Floor is rusty

Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

AC Condition: ☐ Cold ☒ Unknown ☐ No AC

Air Bags: ☐ Driver's Side ☐ Dual

☐ Cruise Control ☒ Tilt Steering ☐ Remote Mirrors ☐ Climate Control

Power: ☒ Steering ☐ Windows ☐ Door Locks ☐ Seats

Additional Equipment: _____

Manufacturer _____ Model _____ Serial # _____

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____

Location of Asset: 800 Coal Heritage Road Bluefield WV 24701