

# Vehicle Inspection Form

Inventory ID: \_\_\_\_\_

Asset Number: \_\_\_\_\_

Fair Market Value: \_\_\_\_\_

**Short Description:**

Year 2003 Make Ford Model F250 Super Duty

VIN: 3FTNF27L83MB16778 Title: ☒ Clean Title ☐ Salvage Title ☐ No Title  
☐ Court Documents Only ☐ SF97 Form ☐ Other

Odometer: Does not work ☐ Miles ☐ Kilometers ☐ Hours Odometer Accurate? ☐ Yes ☐ No ☐ Unknown

**Long Description:**

This Vehicle: ☐ Starts ☐ Starts with a Boost & ☐ Runs/Drivable ☐ Engine Runs ☒ Does Not Run ☐ For Parts Only

Engine- Type: 5.4 L, V 8 ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☐ Runs ☒ Needs repair ☐ is in unknown condition

Repairs needed: Does not fire

This vehicle was maintained every 5,000 ☐ Days ☐ Hours ☒ Miles/Kilometers

Date Removed from Service: Unknown Maintenance Records: ☐ Available ☒ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed: \_\_\_\_\_

Drivetrain: ☐ 2 Wheel Drive ☒ 4 Wheel Drive Condition: Good

**Exterior:**

Color: white Windows: ☒ No Cracked Glass ☐ Cracked

Minor: ☒ Dents ☐ Scratches ☒ Dings Tire Condition: good Tread: \_\_\_\_\_ #Flat \_\_\_\_\_ Hubcaps # \_\_\_\_\_

Major Damage to: \_\_\_\_\_

Additional Damage: \_\_\_\_\_

Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☐ Impressions Remain ☐ No impressions

Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

**Interior:**

Color grey ☐ Cloth ☐ Vinyl ☒ Leather

Damage to Seats: Has hole in drivers side

Damage to Dash/Floor: \_\_\_\_\_

Radio: ☒ Stock or ☐ Brand & Model: \_\_\_\_\_ ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

AC Condition: ☐ Cold ☐ Unknown ☒ No AC

Air Bags: ☐ Driver's Side ☐ Dual

☐ Cruise Control ☐ Tilt Steering ☐ Remote Mirrors ☐ Climate Control

Power: ☒ Steering ☐ Windows ☐ Door Locks ☐ Seats

**Additional Equipment:**

Manufacturer \_\_\_\_\_ Model \_\_\_\_\_ Serial # \_\_\_\_\_

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand \_\_\_\_\_ ☐ Hitch: Type \_\_\_\_\_

Location of Asset: 800 Coal Heritage Road Bluefield WV 24701