

Truck Tractor Condition Report:

Equipment Information:

Unit No:	_____	Engine Information:	_____
Year:	2002	Year:	2002
Make:	Peterbilt	Make:	Detroit
Model:	357	Model:	60
VIN/SN:	1NPALROX82N572719	SN:	_____
KM/Hrs.:	83003	Fuel Type:	Diesel
		HP:	_____

Equipment Condition:

Mechanical Condition: Fair - Starts and operates but some parts require repair or replacement.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

AC/Heat Functional: _____

Leaks Present: Not Seen

Engine Displacement: 11.1

Number of Cylinders 6

Sleeper (if Applicable): Length: _____

of Bunks: _____

Aux Power Unit? _____

Additional Equipment: _____

Transmission:

Transmission Make: _____

Auto / Manual: Automatic

Number of Speeds: _____

Truck Moves FWD/REV: Both

Comments: Its reported the unit has a cracked frame

Chassis:

Frame Rails: Double

Notes: _____

Suspension: Air

Notes: _____

Wheel Base: _____ in.

Axle Weight Ratings (LBS): GVWR: 64,000 Front Axel: 18,000 Rear(s): 46,000

Tire Size: Front: 18/22.5

Rear(s): 11/22.5

Comments: _____

Specialized Equipment:

Type: _____ Details: _____

Type: _____ Details: _____

Notes: _____

Notes: _____